

Oil Field Environmental Incident Summary

Incident: 20150609182106 **Date/Time of Notice:** 06/09/2015 18:21

Responsible Party: Petro Harvester Operating Company LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: Gwendolyn CTB

Field Name: FLAXTON

Well File #:

Date Incident: 6/9/2015 **Time Incident:** 10:00 **Facility ID Number:** 209647-01

County: BURKE **Twp:** 163 **Rng:** 90 **Sec:** 18 **Qtr:** SW NW

Location Description: Gwendolyn CTB is located approximately 2,000' FNL and 100' FWL of Section 18 T163N R90W

Submitted By: Gary Watson

Received By:

Contact Person: Mark Bonnie
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1.5 Mile

Distance Nearest Water Well: 1.5 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	9	Barrels		
Brine	20	Barrels	19	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No explosive risk or health hazards.

Areal Extent:

The affected area off the facility site in the ditch area is approximately 30' x 3'

Potential Environmental Impacts:

Surface water and groundwater not impacted. Minimal impact to soils located in the off-facility site ditch area.

Action Taken or Planned:

Jim Potts-NDIC field inspector was notified telephonically. The landowner and tenant farmer were notified and authorized the clean-up to proceed. The fluids were vacuumed up and the affected facility and off-facility soil will be immediately scraped/dug up, collected and hauled to an approved disposal facility.

Wastes Disposal Location: An approved disposal facility.

Agencies Involved:**Updates**

Date: 6/10/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, impacted areas off location. Followup is required.

Date: 6/19/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Area shows signs of cleanup. No water seen. No staining seen. Area is dry. Excavator and roll off container on well pad. Scraped/impacted area does appear to be in ditch and as stated 30 feet by 3 feet.